# CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BCF OIL REFINING

CONTRACT NO. 68-S2-99-07

ORDER NO.: 19

DATE(s): 2/11/01

SITE/SPILL NO.: PU

SHIFT:24 hour

EPA REGION: II

OSC: Thomas P. Budroe

CONTRACTOR: WRS Infras.& Env., Inc.

WORK ORDER #59

MONITORS: None

RM: Bob Moody

#### DESCRIPTION OF WORK TO BE PERFORMED

1) Provide form 1900-55s to the OSC for approval.

2) Continue providing 24 hour security for the Site. One person acting as the guard will be on-site at all times. Each guard will work an eight hour shift. Each quard will key-in at the appropriate time and location at each key-box. The guard will periodically inspect the site for any releases, spills, leaks, fires, etc.

3) Continue heating tanks 11, 12 and 17 with steam.

### NUMBER OF PERSONNEL AUTHORIZED

0-RESPONSE MANAGER 0-FOREMAN 3-CLEANUP TECHNICIAN(S) 0-PCT 0-CHEMIST 0-EQUIPMENT OPERATOR 0-LAB TECH 0-T&D Coordinator

#### EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED

ITEM	QUANT.	ITEM	OUANT.
PICK UP TRUCK (1/4 TON)	.2	FAX	1 .
OVERPACKS	0	PASSENGER VAN	0
BACKHOE	0	LAPTOP COMPUTER	0.
PORTABLE BOILER	Ĺ	COMPUTER PRINTER	2
PHOTOCOPIER	1	Radio-handheld	3

I CERTIFY THAT THE ABOVE WORK IS ORDERED AND AUTHORIZED BY THE CONTRACTOR IN THE PERFORMANCE OF THE ABOVE CITED DELIVERY ORDER

SIGNATURE OF ON-SCENE COORDINATOR

I ACKNOWLEDGE RECEIPT OF THIS WORK ORDER.

SIGNATURE OF CONTRACTOR'S REPRESENTATIVE

### CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BCF OIL REFINING

ORDER NO.: 19

SITE/SPILL NO.: PU

EPA REGION: II

CONTRACT NO. 68-S2-99-07

DATE(s): 2/11/01

SHIFT:24 hour

OSC: Thomas P.Budroe

WORK ORDER #59

MONITORS: None

RM: Bob Moody

# DESCRIPTION OF SUPPLIES REQUIRED

Amendments:				
SIGNATURE	OF	ON-SCENE COORDINATOR		
SIGNATURE	OF	CONTRACTOR'S REPRESENTATIVE		